





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu








Position

1 = A 962 872 XX	14 = A 962 529 NU
3 = A 962 998 NU	15 = A 961 332 NU
4 = A 962 870 XX	18 = A 962 594 NU
5 = A 962 871 XX	19 = A 961 810 NU
6 = A 963 427 NU	20 = A 962 595 NU
7 = A 962 229 NU	21 = B 960 242 XX
8 = A 962 230 NU	22 = A 961 073 XX
9 = A 963 432 NU	24 = A 963 651 NU
10 = A 962 563 NU	25 = A 960 395 NU
12 = A 962 568 NU	A 960 196 NU







CERATHERM 100
A 4623 .. A 4624 ..

0610 / A 866 247
(+ A 865 612)
Made in Germany



Roentgenstrasse 9
54516 Wittlich
Germany





	P	bar		MAX. 10		5		Q (3 bar)
	T	°C		MAX. 80		65		l/min
				40		40		20,5

