








Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservdeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Застасні частини / Резервни делови / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu




Pos.	Part No.	21	A 963571 AA
4	A 963523 NU	23	A 860899 NU
6	A 963925 NU	24	A 961649 NU
7	A 963952 NU	25	A 963176 NU
8	A 963949 NU	26	A 860945 AA
10	A 960500 NU	27	A 860944 AA
12	A 963783 NU	28	A 962397AA
15	A 963954 NU	29	A 963309 NU
17	A 963526 NU	30	A 6680 AA
20	A 860902 AA	31	A 6677 AA



CERALINE
A 6939 ..








1119 / A 868 449
 (+ A 865 612)
 Made in Germany




Ideal Standard International NV
 Corporate Village - Gent Building
 Da Vincilaan 2
 1935 Zaventem
 Belgium

www.idealstandardinternational.com





Pressure 0,3 MPa 3 bar	Temperature 50°C	Temperature 16°C	0	1	2	3	4	5	6	7	8	9
			°C	°C	°C	°C	°C	°C	°C	°C	°C	°C
	50°C	16°C	49,5	49,5	48	46	42,5	41	37	33,5	31	28
	65°C	16°C	65	65	63,5	60,5	57	53,5	49	44,5	39	34,5
	81°C	16°C	81	81	78,5	73	69	63,5	56	49	42,5	36



Pressure P bar	Temperature T °C	Pressure 0,5 MAX. 10	Temperature MAX. 80	Pressure 5 1	Temperature 65 40	Pressure Q (3 bar)	Temperature I/min 20,5