







DN32 PN6
Horizontal

Use two stud bolts



DN50 PN6

Use 4 bolts

